

## Release Notes

---

### Scope

Required for all Sensys Networks customers interested in the new functionality and bug fixes incorporated in TrafficDOT 2.16.12.

### What's in this Release?

#### Bug Fixes

#### **Update Repeater Names to Match Product Selection: FlexNode vs FlexRepeat vs FlexRepeat Solar [15302]**

TrafficDot now shows proper visible labeling for solar repeaters vs FlexNode.

#### **bdc not broadcasting to all available interfaces [15387]**

bdc now broadcasts on all available interfaces to discover available gateways. This was first reported on windows 7. Previously, it only worked on a first available interface.

#### **APCC 2.x/SPP.40 to Solar Repeater 222.57 gets \* on downstream channel change [15423]**

When setting downstream channel on a new Solar Repeater, an asterisk \* indicating the pending change was set in TD2 and never went away. Sensors behind this channel never appeared. This has been fixed now and does not require a reboot of APCC to proceed.

### Disclaimer

This information is furnished for informational use only, is subject to change without notice, and should not be construed as a commitment by Sensys Networks, Inc. Sensys Networks, Inc. assumes no responsibility or liability for any errors or inaccuracies that may appear in this document or any software that may be provided in association with this document. Except as permitted by such license, no part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means without the express written consent of Sensys Networks, Inc.